

No columns that require replacement this year just the usual Phosco P109 replacements plus the next phase of LED lights.

Columns 54, 55, 56, Netherfield Hill/Road three more SL8's required to complete this area. (£975 + Vat.)

Columns 63-66, Virgins Lane, four new SL8's required (to get rid of 100w Son-t's and reduce energy consumption). (£1300 + Vat.)

Columns 67-70, Whatlington Road, these are Sodium Jet lanterns, four new SL8's required to reduce energy consumption. (£1300 + Vat.)

Columns 71-74, Oaklands Road, these are tatty Sodium SRL's, three new SL8's required to reduce energy consumption. (£975 + Vat.)

Column 88, The Cloisters, damaged P109, requires new Worcester lantern. (£1050 + Vat.)

Columns 113, 122-128, Marley Lane, these are all 100w Son-t lights, 20+ years old, no spares. Eight new SL8's required (to get rid of 100w Son-t's and reduce energy consumption). (£2600 + Vat.)

Column 130, Coronation Gardens, pole box door missing. Replace pole box. (£260 including connection)

Column 131, Coronation Gardens, column d/b pole box surrounded with Ivy, needs cut back. (£95 + Vat.)

Column 160, Knights Meadow, troublesome P109, replacement Worcester lantern required. (£1050 + Vat.)

Column 171, Raven Court, door and column slightly creased (advisory only).

Column 174, Swallow Drive, column has been nudged by vehicle, requires RTV (in Tarmac). (£275 + Vat.)

Column 183, Battle Hill, column in dense bushes on main road requires RTV. (£320 + Vat.)

Column 202, Starrs Mead, another tired P109, badly discoloured and stained, requires new Worcester lantern. (£1050 + Vat.)

Total cost of all work £11,250 + Vat.

On completion of the above work, just the roads off North Trade Road (for LED conversion/reduce energy consumption) plus the ongoing replacement of the P109's will be left for next year.